



A2140

SERVICE PARTS LIST

THE M.G. Series MGA TWIN CAM

Item No.	DESCRIPTION	Commencing (C) 501		Qty. per Vehicle		Unit of Issue	Type of Vehicle	MODIFICATIONS			REMARKS
		Part Number	Illus. No.	RHD	LHD			New Part Number	Change Point	Amdt. No.	
	<u>REAR SHOCK ABSORBER</u>										
1	Shock absorber—rear—R.H.	AHH5029		1	1						
2	Shock absorber—rear—L.H.	AHH5030	L1	1	1						
3	Link—shock absorber	97H2031	L2	2	2						
4	Nut—link to bracket	FNZ108	L3	2	2						
5	Washer for nut (spring)	LWN208	L4	2	2						
6	Bolt—shock absorber to frame	HBZ0728	L5	4	4						
7	Nut for bolt	FNZ107	L6	4	4						
8	Washer for nut (spring)	LWZ207	L7	4	4						
9	Washer for nut (plain)	PWZ107	L8	8	8						